

WESTTOWN TOWNSHIP
PUBLIC WORKS DEPARTMENT
MONTHLY REPORT FOR AUGUST 2016

ROADS

- ◆ Dunvegan Road culvert replacement completed.
- ◆ Roadside mowing – 2nd seasonal cutting was completed.
- ◆ One after-hours deployment of a traffic signal generator at 926/S. Concord Road due to a power failure.
- ◆ Road traffic lines were painted throughout the entire township.
- ◆ Removed overgrown vegetation and cleaned debris from the stormwater gutter along the 700 block of Oakbourne Road.
- ◆ Pruned the traffic island trees in the Pleasant Grove development.
- ◆ 202/Skiles and 3/352 traffic signals had detection cameras installed.
- ◆ A road employee attended a continuing education seminar on drainage.
- ◆ 3rd seasonal cutting of roadside vegetation was completed.
- ◆ Filled potholes as necessary throughout the township.
- ◆ Straightened and replaced faded and damaged street signs.

PARKS, BUILDINGS, AND OPEN SPACE

- ◆ Three lawn cuts this month.
- ◆ Provided administrative courier service, zoning postings, etc.
- ◆ Checked operation and fluid levels on all standby generators.

OAKBOURNE PARK AND MANSION HOUSE

1. Assisted in the Dogwood walking trail restoration Eagle Scout project.
2. Repaired two failed sewage pumps and vacuumed grease from the mansion ejector system.
3. Secure unused doors accessing the rear fire escape in preparation for removal.
4. Relocated approximately 200 yards of topsoil to the park for a future landscape berm project.
5. Managed rental events and assisted in set-up.
6. Trash, recyclables, and rest room cleaning and maintenance.

PARKS AND OPEN SPACE

1. Open space field mowing completed.
2. Inspected all playground structures for safety hazards.

3. Inspected stormwater retention basins for proper operation.

WASTEWATER

- ◆ PGPS failed pump was repaired and placed into service.
- ◆ An employee attended continuing education seminar for license credits.

EQUIPMENT MAINTENANCE AND REPAIR

- ◆ 67-44 - Tractor transmission was replaced.
- ◆ 67-18 Driver's window track assembly was replaced.
- ◆ 67-10 Exhaust gas sensor was replaced and computer system was reprogramed as a factory recall.
- ◆ CAT wheel loader had the radiator/oil cooler replaced due to severe salt corrosion.
- ◆ 67-19 PTO solenoid was replaced.

FUTURE PROJECTS

- ◆ Annual re-lamping of all exit and emergency lights.
- ◆ Re-contouring one stormwater basin and remove accumulated silt.

MARK GROSS
DIRECTOR OF PUBLIC WORKS